

Wabash ABS PCM air leak

Problem: Air leaking from bottom of ABS valve when service brake applied.

Cause: Debris stuck in quick release valve part of PCM.

Repair:

1. Insure that wheels on trailer have been chalked.
2. Remove air line from the inlet side of PCM by pushing in on the brass ring and pulling out on the air line.
3. Using a short section of air line and an air hose quick disconnect set up insert the air line end into the PCM.
4. Insure that you hold on to the air line and quick disconnect now connect the shop air hose and build to full shop pressure.
5. Holding the air line section and the shop air hose in each hand disconnect the two lines making sure to direct the exhausting air from the air line section away from you. (This may need to be repeated before all debris has been cleared)